Southwest Florida Office 5051 Castello Drive, Suite Naples, FL 34103

Central Florida Office 1460 Breezy Way Spring Hill, FL 34608 (For all shipments)

Phone: (352) 684-7275 Email: alex@eryouengineering.com

Fax: (800) 660-6724

CERTIFICATE OF COMPLETION OF THIRD-PARTY UL 2447 EVALUATION

July 31, 2018

Mr. Paul Reber **Icon Containment Solutions** 905 North Main Street Suite D1 North Salt Lake, UT 84054

Dear Mr. Reber:

Reference Number: ICS07312018

UL 2447 "Outline of Investigation for Containment Sumps, Fittings and

Accessories for Fuels"

Products Evaluated: Icon SplitRepair Sump Penetration and Test Reducer Fittings

Sump Damage Repair (cracking, holes, seam leaks).

Our UL 2447 Third-Party Certification inspection and testing process of your products listed above has been completed and they were determined to comply with the above listed requirements.

While the products tested met the UL 2447 requirements, you should be aware that UL has the exclusive right to allow your firm to apply the UL label to your products as their labeling program includes an extensive ongoing UL quality control program.

Respectfully,

N.D. Eryou, PhD, P.E.

ICON - UL 2447 Evaluation 082218